



Condition of Structure

- Good
- Fair
- Poor



Note : Although many sections of the I-84 and Route 8 structure are fair or better, two major sections were rated poor. These include the I-84 EB bridge and the I-84 WB bridge.

0.3 0 0.3 0.6 0.9 Miles



Condition of I-84 Structures

I-84 West of Waterbury (WOW)
Needs and Deficiencies Study

Source : ConnDOT



Figure 2-7